Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080135-4

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2761 E. COLORADO ST., PASADENA, CALIF.

No. 11329

RECEIVED FROM Rodell Rubber Company

DATE REC'D 2-21-57

P.O. NO. Petty Cash

VENDOR PACKING SLIP NO. 02366

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		69	0	22	1				

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
75	732402-070 1/4 inch X 1/4 inch Strip ing sponge - closed cell	✓		
	Total cost Rec. #11329 & #11328 $4.76			
	To supersede No. #11326			

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 2-[illegible]-57 REJECTS RETURNED ON SHIP. MEMO NO.

RMC-1069

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2761 E. COLORADO ST., PASADENA, CALIF.

No. 11340

RECEIVED FROM FLINT #5

DATE REC'D 2-22-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	OR	ACCT. OR W.O. NO. / S.O. NO.
	322		C71	0	22					

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
1	732173 Hub Roller	1 ✓		
	IPS #AOC3283			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080135-4

RECEIVED BY [illegible] INSPECTED BY [illegible] DATE 2/28/57 REJECTS RETURNED ON SHIP. MEMO NO.

RMC-1069